

CABLE CUT




Table IV, left pointer, Defect No. 114, Major defect - Exposed seam laminations. Right pointer, Insignificant Defect. Seam laminations not exposed by slight cable cut.