

INCOMPLETE CLOSURE




Table IV, Defect No. 101, Major defect. The lid was not crimped by the second roller of closing machine to complete the closure.