

DENT




Table IV, Defect No. 208 - Minor defect. Dent on end seam forcing it inward to such an extent that the counter sink (channel next to end seam) and body are involved, but no sharp ridges are evident.